





# ALL HARNESS' GET MALE PLUGS SENSORS GET FEMALE SOCKETS


TO WATER CONTROL VALVE  
AND F.B. SENSOR ON RX-MILL




## SLURRY OPTION




EMULSION TEMP SENSOR PLUG  
8 FT 205973



90 INCHES 205972




8 FT 205971



10 CONDUCTOR SHIELDED CABLE FROM CONTROL BOX TO FRONT OF R1500  
SHIELD TERMINATED IN PI AT THE CONTROL BOX END ONLY

205970



8 FT 205974



CONNECTORS ON SIDE OF CONTROL BOX

TO PUG  
EMULSION  
PUMP

TO RX-MILL  
WATER  
VALVE

RX-MILL  
EMULSION

TO ROTO MILL

TO CIR EMULSION  
ELC BOX POWER